

*Crestwood Lake Overflow Pushes Dirt Onto Roadway*



The overflow from Crestwood Lake, Allendale, was so great that it forced much of the dirt and stones pictured above onto West Crescent Avenue near the Erie Railroad underpass. Debris was stacked several feet into space and County steam-shovels have tackled the process of clearing

away the dirt and rocks. It is estimated that the job will require twelve working days. On the other side of the crossing is a car which was badly damaged in an attempt to brave the waters. (Photo by Chilton-Butler).